NOTE:

THIS HARNESS REQUIRES THE USE OF A NEW HORN RELAY TO PROVIDE A POWER JUNCTION FOR THE BATTERY CABLE SECONDARY LEAD.

USE DELCO HORN RELAY PART NUMBER D-1709A OR GM PART NUMBER 12339243.



INSTRUCTION SHEET
FRONT LIGHT HARNESS
1962 CHEVROLET PASSENGER
WITH INTERNAL VOLTAGE REGULATOR

PART NO.

92963625